

This is a Maintenance Report generated by Cappsure for the property below.

Property Name : **58 - Westwind**

Creator : Marcos Lopez

Date : **01/14/2019**

S.NO	Item Name	Notes
1	CHECK IN-CHECK IN	
2	UNSATIS. VINE NEEDS TRIMMING- UNSATIS. VINE NEEDS TRIMMING	Vines have been well maintained, however need to start trimming them back closer to the wall to avoid some of the detaching issues that are occurring in other areas.

**Picture: 1**



**Picture: 2**



S.NO	Item Name	Notes
2	UNSATIS. VINE NEEDS TRIMMING- UNSATIS. VINE NEEDS TRIMMING	Vines have been well maintained, however need to start trimming them back closer to the wall to avoid some of the detaching issues that are occuring in other areas.