LANDSCAPE ASSESSMENT DISTRICT INSPECTION CHECKLIST



LOCATION/ DISTRICT NUMBER:		DATE:			
		6-22-17			
#57 GOLDEN CI	TATE STOPAGE	FOLLOW UP DATE:			
ONTRACTOR:		INSPECTOR:			
	outhacion.		JOSEPH BEARDSHEAR		
KANFILO LANDSCAPING		CONTRACTOR REP:			
P. 451 P. 11		JAVIER GUTTERREZ			
CHECK ISSUE(S) IF UNSATISFACTORY, NOTI	E LOCATION, NUMBER IF MU	ULTIPLE AND NOTE BELOW, AND AN	Y HISTORY OF NON-COMPLIANCE. WRITE"NA" WH		
CHECK ISSUE(S) IF UNSATISFACTORY, NOTI APPLICABLE. INDICATE "OK" ON FOLLOWU	E LOCATION, NUMBER IF MU IP. Locations	ULTIPLE AND NOTE BELOW, AND AN	Y HISTORY OF NON-COMPLIANCE. WRITE"NA" WHI		
CHECK ISSUE(S) IF UNSATISFACTORY, NOTI APPLICABLE. INDICATE "OK" ON FOLLOWU IRRIGATION:	ır.				
APPLICABLE. INDICATE "OK" ON FOLLOWO	ır.				
IRRIGATION:	ır.				
IRRIGATION: Breaks/Leaks	ır.				
IRRIGATION: Breaks/Leaks Poor Coverage	ır.		Follow-up/Status		
IRRIGATION: Breaks/Leaks Poor Coverage Too Wet	ır.		Follow-up/Status		

SHRUBBERY:	COAL COAL COAL COAL COAL COAL COAL COAL
Hedge Trim/Shape	BOOGANVILLA TRIMMEN
Dead Material	
Poor Health	

Trim			
Poor Health	1 H		
Detachment	F F	19	

TREES:		
Pruning		
Poor Health/Dead	TWO TREES ON W/END STILL	
Stalks	STKUCICALING	

TURF:	2 1	
Mow/Edge		
Poor Health		
Other		

10/18/2016

Medians Turf

Hardscapes

LANDSCAPE MAINTENANCE DISTRICT INSPECTION CHECKLIST

Page 1 of 3

LOCATION/DISTRICT NUMBER:	DATE: 6-22-17	
#57 GOLDEN STATE STORAGE	000 /1	

	Locations	History	Follow-up/Status
GROUND COVER/ PLANT BEDS:			
Overgrown			
Dead			
Poor Health		1	
PESTS:			
Gopher			
Insect			
Other			,
RESTROOMS:			
Not Clean			
Faulty Plumbing			
Faulty Electrical			
WALKWAYS/PATHS:			
Obstruction/Trip			
Fiber Coverage			
Dog Bags			
Fountains			
Exercise Stations			
Faulty Lighting			
VANDALISM:			
Graffiti			
			
Missing/Damaged items			
FENCING:	2 3		
Posts: Loose			
Posts: Missing Caps			
Panels: Bent Bars			
Panels: Missing Bars			
Panels: Missing Bolts			
Gate: Hinge			
Gate: Locking Mechanism			
Gate: Lock Missing		ar and problems	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Gate: Swings Freely			
Paint: Scratches			il a
Paint: Rust			
Paint: Flaking			
Paint: Chipped			
Other: Plants Too Close			-

10/18/2016

LANDSCAPE MAINTENANCE DISTRICT INSPECTION CHECKLIST

Page 2 of 3

LOCATION/DISTRICT NUMBER:		DATE: 6-22-	-17
COUNTY SINI	Locations	History	Follow-up/Status
Other: Sprinklers Hitting Fence			
Other:			
MISC:			_ 1,
Trash			
Excessive Leaf Litter			
Hazardous Item			
Other			
Other			
Turf Fertilizer Due (6x Per Yr) Spring Broad Leaf Turf Pesticide Application Due Shrub & Ground Cover	October Aearifica Fall Broad Leaf Tu Application Due Palm Fertilizer Du	ırf Pesticide	May Aerification Due October Dethatch Due
Fertilizers Due (3x Per Yr)		- (27)	
INSPECTORS SIGNATURE:	DATE:		D THIS INSPECTION WALKTHROUGH
BEVIEW ADMINISTRATORS SIGNAT	URE: DATE:	CONTRACTOR/RE	PRESENTATIVE SIGNATURE:
Additional Notes:		00	
		100	P
		-	

10/18/2016

LANDSCAPE MAINTENANCE DISTRICT INSPECTION CHECKLIST

Page 3 of 3