

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578



Property Details

Property Name : **43 - Greenbelt**
Creator : Christopher Parker
Date : **03/26/2019**

Item Name

UNSATIS. WEEDS IN TURF-UNSATIS. WEEDS IN TURF

Notes : Please treat for weeds.

UNSATIS. TREE WELLS-UNSATIS. TREE WELLS

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

Notes : Bench needs replacing.

INSPECTION TURF-UNSATISFACTORY MOW & EDGE OF TURF AREAS

Notes : Grass clumping and tracks on sidewalk must be cleaned from walkways.

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

Notes : All benches need painting.

SIDEWALK INSPECTION-UNSATIS. LIFTED SIDEWALK

UNSATIS. POLE LIGHT-UNSATIS. DAMAGED POLE LIGHT

Notes : Exposed electrical.

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Item Name

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

UNSATIS. DAMAGED LIGHT-UNSATIS. LIGHT POLE DAMAGE

Notes : Globe broken.

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

UNSATIS. SIGN MISSING/DAMAGED-UNSATIS. SIGN NOT LEGABLE

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

UNSATIS. MUTT-MITT STATION-UNSATIS. DAMAGED MUTT-MITT STATION

UNSATIS. MUTT-MITT STATION-UNSATIS. MISSING MUTT-MITT STATION

Notes : There are no active mutt mit stations throughout Green belt and pet waste is all over.

UNSATIS. TRASH RECEPTACLE-TRASH RECEPTACLE THAT HAS DETERIORATION OR DAMAGE

Notes : Rusted - needs replacing.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



Item Name

UNSATIS. WEEDS IN TURF-UNSATIS. WEEDS IN TURF

Notes : Please treat for weeds.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. TREE WELLS-UNSATIS. TREE WELLS

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

Notes : Bench needs replacing.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

INSPECTION TURF-UNSATISFACTORY MOW & EDGE OF TURF AREAS

Notes : Grass clumping and tracks on sidewalk must be cleaned from walkways.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

Notes : All benches need painting.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

SIDEWALK INSPECTION-UNSATIS. LIFTED SIDEWALK

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POLE LIGHT-UNSATIS. DAMAGED POLE LIGHT

Notes : Exposed electrical.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

MAINTENANCE REPORT

City of Oxnard


1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POLE LIGHT-UNSATIS. POLE LIGHT MISSING PANEL

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. DAMAGED LIGHT-UNSATIS. LIGHT POLE DAMAGE

Notes : Globe broken.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SIGN MISSING/DAMAGED-UNSATIS. SIGN NOT LEGIBLE

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. SEATING-BENCH DETERIORATION, DAMAGE

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. MUTT-MITT STATION-UNSATIS. DAMAGED MUTT-MITT STATION

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. MUTT-MITT STATION-UNSATIS. MISSING MUTT-MITT STATION

Notes : There are no active mutt mit stations throughout Green belt and pet waste is all over.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. TRASH RECEPTACLE-TRASH RECEPTACLE THAT HAS DETERIORATION OR DAMAGE

Notes : Rusted needs replacing.