

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578

### **Property Details**

Property Name : Waterways Harbor Island

Creator : J. Beardshear

Date : 08/27/2019

#### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** Broken 6 inch pop up in this area.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Plant material overgrown and completely blocking irrigation and creating excess runoff throughout District.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes:** Pop-up sideways causing insufficient coverage.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes:** Two nozzles clogged causing insufficient coverage need to be addressed.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes: Needs to be replaced with a 10' adjustable to create sufficient coverage

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes: Quarter nozzle needs to be replaced with an adjustable 10 ft nozzle for sufficient coverage

UNSATIS, POOR COVERAGE-UNSATIS, POOR COVERAGE

**Notes :** Pop-up in the wrong place. Needs to be moved near Turf and away from electrical enclosure.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK



OXNARD

City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



#### **Item Name**

Notes: Nozzle broken needs to be replaced. Causing flooding.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Two pop-ups being blocked from turf. Turf needs to be removed from around pop-ups to allowpop-ups to come up.

INSPECTION TURF-UNSATISFACTORY MOW & EDGE OF TURF AREAS

**Notes :** Turfing mode at way too high of a level, Turf to be mowed at 1 inch to keep edges of turf lowenough for pop-ups to operate properly.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 10 ft 1/2 Hunter nozzle needs to be replaced.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 10ft pool pop-up nozzle missing. Needs to be replaced.

UNSATIS. VALVE/CONTROLLER MALFUNCTION-UNSATIS. VALVE/CONTROLLER MALFUNCTION

**Notes:** Controller valve six is not operating. Valve needs to be looked at and flushed.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** Broken 6in Rainbird pop-up in planter.

UNSATIS, POOR COVERAGE-UNSATIS, POOR COVERAGE

**Notes :** Two 10ft adjustable irrigation nozzles needed to replace current nozzles due to poor coverage concerns.

UNSATIS, POOR COVERAGE-UNSATIS, POOR COVERAGE

**Notes:** Crooked nozzle creating coverage concerns. Needs to be straightened.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 6 inch Rainbird pop-up not operating. Needs to be replaced.





1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



#### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 10 foot nozzle is broken and needs to be replaced.

UNSATIS WATERING TOO DRY-UNSATIS WATERING TOO DRY

**Notes :** Station 13 completely dry, contractor needs to add more time to the clock.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes: Broken 6 inch pop up in this area.




# City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 2



## **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Plant material overgrown and completely locking irrigation and creating excess runoff throughout District.




## City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes: Pop-up sideways causing insufficient coverage




# City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



**City of Oxnard** 

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 2



## **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes: Two nozzles clogged causing insufficient coverage need to be addressed.




City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes: Needs to be replaced with a 10' adjustable to create sufficient coverage.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes: Quarter nozzle needs to be replaced with an adjustable 10 ft nozzle for sufficient coverage.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes**: Pop-up in the wrong place. Needs to be moved near Turf and away from electrical enclosure.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** Nozzle broken needs to be replaced. Causing flooding.



# City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1




City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 2



## **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Two pop-ups being blocked from turf. Turf needs to be removed from around pop-ups to allow pop-ups to come up.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



## **Item Name**

### INSPECTION TURF-UNSATISFACTORY MOW & EDGE OF TURF AREAS


**Notes :** Turfing mowed at way too high of a level, Turf to be mowed at 1 inch to keep edges of turf low enough for pop-ups to operate properly.

City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 10 ft 1/2 Hunter nozzle needs to be replaced.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 10ft pool pop-up nozzle missing. Needs to be replaced.

City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK


Notes: Broken 6in Rainbird pop-up in planter.

City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Two 10ft adjustable irrigation nozzles needed to replace current nozzles due to poor coverage concerns.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Crooked nozzle creating coverage concerns. Needs to be straightened.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 2



## **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 6 inch Rainbird pop-up not operating. Needs to be replaced.



City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes:** 10 foot nozzle is broken and needs to be replaced.




City of Oxnard

1060 Pacific Ave specialdistricts@oxnard.org (805) 385-7578



Picture: 1



### **Item Name**

UNSATIS WATERING TOO DRY-UNSATIS WATERING TOO DRY

Notes: Station 13 completely dry, contractor needs to add more time to the clock.