MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Property Details

Property Name	: **51 - Pfeiler**
Creator	: Jose Sanchez
Date	: **12/02/2019**

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken rainbird 12 inch pop-ups.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-ups.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Please have contacted check irrigation possibly a broken lateral

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Please have contractor check irrigation possible lateral break.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken rainbird 12 inch pop-ups.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-ups.

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Please have contacted check irrigation possibly a broken lateral

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Please have contractor check irrigation possible lateral break.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Property Details

Property Name	: **51 - Pfeiler**
Creator	: Jose Sanchez
Date	: **12/02/2019**

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-up.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop up.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Hunter rotor not providing enough coverage

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-up.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop up.

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Hunter rotor not providing enough coverage