

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Property Details

Property Name : **34 - Sunrise Pt/Sunset Cove**

Creator : Jose Sanchez

Date : **08/10/2020**

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-up.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-up on Latigo Ave.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Poor watering coverage on Rainbird rotor T 40.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Check irrigation on planters and the grass outside the basin. Several broken nozzles and Rainbird 12 inch pop-ups. Check water pressure and sizes of nozzles to avoid over spray to the sidewalk.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Poor coverage - rotor watering straight downwards is tilted to the wrong position.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop- up.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Broken Rainbird 12 inch pop-up Latigo Ave.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Poor watering coverage on Rainbird rotor T 40.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Check irrigation in planters and the grass outside the basin. Several broken nozzles and Rainbird 12 inch pop-ups. Check water pressure and sizes of nozzles to avoid over spray to the sidewalk.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Poor coverage - rotor watering straight downwards, rotor is tilted to the wrong position.