MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Property Details

Property Name	:	**39 - El Sueno Promesa**
Creator	:	Jose Sanchez
Date	:	**08/13/2020**

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contactor to check irrigation - not watering causing grass to stress.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - several Rainbird 12 inch pop-ups and nozzles broken.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - several Rainbird 12 in pop-ups and nozzels broken.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Contractor to check irrigation - area not being watered properly (big dry spots).

UNSATIS. VALVE/CONTROLLER MALFUNCTION-UNSATIS. VALVE/CONTROLLER MALFUNCTION

Notes : Contractor to check irrigation as there appears to be valve malfunction, possibly a stuck valve.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 4

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 5

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - not working properly and is causinggrass to stress.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 4

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - several Rainbird 12 inch pop-ups and nozzels broken.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - several Rainbird 12 in pop-ups and nozzels broken.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Contractor to check irrigation - area not being watered properly (big dry spots).

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. VALVE/CONTROLLER MALFUNCTION-UNSATIS. VALVE/CONTROLLER MALFUNCTION

Notes : Contractor to check irrigation as there appears to be a valve malfunction, possibly a stuck valve.