MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Property Details

Property Name	: **42 - Cantabria/Coronado**
Creator	: Jose Sanchez
Date	: **08/11/2020**

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

UNSATIS. POOR HEALTH/DEAD-UNSATIS. POOR HEALTH/DEAD

Notes : Magnolia trees need to be treated for aphids and scale.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 4

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK