

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578



Property Details

Property Name : **51 - Pfeiler**
Creator : Jose Sanchez
Date : **08/10/2020**

Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Contractor to check irrigation as there are several Rainbird 12 inch pop-ups and nozzles that are broken.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contactor to check irrigation as there are several Rainbird 12 inch pop-ups and several nozzles are damaged.

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Contractor to check irrigation as area is not being watered properly and several areas are stressing.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation several Rainbird 12 inch pop-ups that are broken.

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contactor to check irrigation - possible broken lateral and nozzles.

UNSATIS WATERING TOO WET-UNSATIS WATERING TOO WET

Notes : Contractor to check irrigation, area is being watered too much, but also some areas are stressing.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Contactor to check irrigation as there are several Rainbird 12 inch pop-ups and nozzles that are broken.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contactor to check irrigation several Rainbird 12 inch pop-ups and nozzles are damaged.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



Item Name

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

Notes : Contractor to check irrigation as area is not being watered properly and several areas are stressing.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - several Rainbird 12 inch pop-ups are broken.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contactor to check irrigation - possible broken lateral and nozzles.

MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



Item Name

UNSATIS WATERING TOO WET-UNSATIS WATERING TOO WET

Notes : Contractor to check irrigation, area is being watered too much and some areas are stressing.