MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Property Details

Property Name	:	**23 - Greystone**
Creator	:	Jose Sanchez
Date	:	**09/23/2020**

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation area is not being watered properly and there is low pressure on the water - possible lateral break. Also several broken nozzles or clogged nozzles on H St.

UNSATIS WEEDS IN PLANTERS-UNSATIS WEEDS IN PLANTERS

Notes : Contractor to remove all weeds from the planter and tree volunteers.

UNSATIS. REMOVE DEAD SHRUB MATERIAL-UNSATIS. REMOVE DEAD SHRUB MATERIAL

Notes : Contractor to remove all dead shrubs.

UNSATIS. VINE DETACHED-UNSATIS. VINE DETACHED

Notes : Vine is detached from the wall, contractor to fix.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 4

Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

Notes : Contractor to check irrigation - area is not being watered properly - lowpressure on the water - possible lateral break. Also several broken nozzles or clogged nozzles on H St.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 2

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 3

Item Name

UNSATIS WEEDS IN PLANTERS-UNSATIS WEEDS IN PLANTERS

Notes : Contractor to remove all weeds from the planter tree volunteers.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. REMOVE DEAD SHRUB MATERIAL-UNSATIS. REMOVE DEAD SHRUB MATERIAL

Notes : Contractor to remove all dead shrubs.

MAINTENANCE REPORT

City of Oxnard
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

Picture: 1

Item Name

UNSATIS. VINE DETACHED-UNSATIS. VINE DETACHED

Notes : Vine is detached from the wall, contractor to fix.