# MAINTENANCE REPORT

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

## Property Details

| | |
|---|---|
| Property Name | : **32 - Oak Park** |
| Creator | : Jose Sanchez |
| Date | : **09/29/2020** |

## Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Contractor to check irrigation - stuck valve on Station One.

UNSATIS. TREES NEED PRUNING-UNSATIS. TREES NEED PRUNING

**Notes :** Canary Island Palm trees and the pine trees need to be pruned.

SATIS. INSPECTION SHRUBBERY-SATIS. INSPECTION SHRUBBERY CORRECTED & COMPLETE

**Notes :** Contractor to trim lantana  - sign blocked.

# MAINTENANCE REPORT

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

**Picture: 1**

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

**Picture: 2**

# MAINTENANCE REPORT

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

**Picture: 3**

## Item Name

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Contractor to check irrigation - valve stuck on Station One.

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

**Picture: 1**

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578


**Picture: 2**

## Item Name

UNSATIS. TREES NEED PRUNING-UNSATIS. TREES NEED PRUNING

**Notes :** Canary Island Palm trees and pine trees need to be pruned.

# MAINTENANCE REPORT

**City of Oxnard**
1060 Pacific Ave
specialdistricts@oxnard.org
(805) 385-7578

**Picture: 1**

## Item Name

SATIS. INSPECTION SHRUBBERY-SATIS. INSPECTION SHRUBBERY CORRECTED & COMPLETE

**Notes :** Contractor to trim lantana - sign blocked.