

# MAINTENANCE REPORT

## City of Oxnard

1060 Pacific Ave  
specialdistricts@oxnard.org  
(805) 385-7578



## Property Details

Property Name : **33 - El Paseo**  
Creator : Jose Sanchez  
Date : **09/14/2020**

---

### Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Broken nozzles along the wall.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Broken rainbow 12 inch pop up and several broken nozzles. Contractor to check irrigation.  
UNSATIS. LEAF LITTER-UNSATIS. LEAF LITTER

---

**Notes** : Excessive leaf litter on the area.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Several broken nozzles along the sidewalk.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Broken rotor and several nozzles need to be replaced in the area.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Possible broken lateral.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Rainbird rotor not functioning.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Broken Rainbird rotor. Contractor to repair.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Broken nozzles along the wall.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Broken rainbow 12 inch pop up and several broken nozzles. Contractor to check irrigation.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



# MAINTENANCE REPORT

City of Oxnard


1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 4



---

## Item Name

---

UNSATIS. LEAF LITTER-UNSATIS. LEAF LITTER

**Notes :** Excessive leaf litter on the area.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Several broken nozzles along the sidewalk.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Broken rotor and several nozzles need to be replaced in the area.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Possible broken lateral.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Rainbird rotor not functioning.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Broken Rainbird rotor. Contractor to repair.