

# MAINTENANCE REPORT

## City of Oxnard

1060 Pacific Ave  
specialdistricts@oxnard.org  
(805) 385-7578



## Property Details

Property Name : **38 - Aldea Del Mar**  
Creator : Jose Sanchez  
Date : **09/30/2020**

---

### Item Name

---

UNSATIS WATERING TOO DRY-UNSATIS WATERING TOO DRY

**Notes** : Contractor to check irrigation - several grass areas are stressing.

---

UNSATIS. TREES NEED PRUNING-UNSATIS. TREES NEED PRUNING

**Notes** : Trees in this area need to be trimmed.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Contractor to check irrigation - possible lateral break and broken Rainbird 12 in pop-up.

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes** : Contractor to check irrigation - broken rotor and broken riser.

---

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes** : Contractor to check irrigation - several nozzles are clogged.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



---

## Item Name

---

UNSATIS WATERING TOO DRY-UNSATIS WATERING TOO DRY

**Notes :** Contractor to check irrigation - several grass areas are stressing.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



---

## Item Name

---

UNSATIS. TREES NEED PRUNING-UNSATIS. TREES NEED PRUNING

**Notes :** Trees in this area need to be trimmed.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Contractor to check irrigation - possible lateral break and broken Rainbird 12 in pop-up.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 3



---

## Item Name

---

UNSATIS. IRRIGATION BREAK/LEAK-UNSATIS. IRRIGATION BREAK/LEAK

**Notes :** Contractor to check irrigation - broken rotor and broken riser.

# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 1



# MAINTENANCE REPORT

City of Oxnard

1060 Pacific Ave

specialdistricts@oxnard.org

(805) 385-7578



Picture: 2



---

## Item Name

---

UNSATIS. POOR COVERAGE-UNSATIS. POOR COVERAGE

**Notes :** Contractor to check irrigation - several nozzles are clogged.